

Date of Inspection: 02/01/2021	District: W. CLanbaron
Division: Rathfriland	Length (km):
Name of the Road: L073 - M2 to Gully	
Scheme/Programme: MAINTENANCE	
Package No.: BR-37R-434	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	UNDBR Maint.
Work is a case of: New Connectivity/Up gradation/ Maintenance	Maint.

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S
b)	Condition of Surfacing	U
c)	Riding Quality	U
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes
g)	Compaction of flank/slope & raincuts if any	U
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S
c)	Condition of railings/slab/approach for Bridges	N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	U
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Note:- Road affected from Heavy Flood. Some
Dist. of Road fully wash out.


02/01/2021
(Signature)

NAME: SUNIL KUMAR

DESIGNATION: T.E.