

FIELD INSPECTION REPORT

Date of Inspection : 23.12.2020
 Division : H.T. & C. District : Nanded
 Name of the Road : Haski Lorry to Chaudhary
 Length (km) : 0.675 km
 Scheme Programme : MAINTENANCE
 Package No. : BR 200 101 Road Id No. :
 Status of the Project : Ongoing Completed Under Maintenance ✓
 Work is a case of : New Connectivity/Up gradation Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/A ✓
b)	Condition of Surfacing	S/A ✓
c)	Riding Quality	S/A ✓
d)	Road Chamber	S/A ✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Compaction of flank/slope & railments if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in flume pipe culverts including its painting	S/SRI ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI NA
c)	Condition of railings/slab approach for Bridges	S/SRI NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	+

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

U

Ranjit Chaudhary

Ranjit Chaudhary
 23.12.2020
 J.F.
 (Signature)