

FIELD INSPECTION REPORT

Date of Inspection: 11/1/2021	District: Chitradurga
Location: 14/5 km	Length (km): 2.71 km
Name of the Road: Pathanur to Chitradurga Bypass	
Name/Programme: MAINTENANCE	
Project No.:	Road Id No.:
Name of the Project: Ongoing/Completed/Under Maintenance	
Is a case of: New Connectivity/Up gradation/ Maintenance	
Parameters to be checked	
Pavement	Remarks
Road Junction condition	S/U
Condition of Surfacing	S/U
Riding Quality	S/U
Road Camber	S/U
Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
Contraction Joints provided or not (CC Pavement)	Yes/No
Compaction of flank/slope & raincuts if any	Yes/No
Cross Drainage	
Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
Condition of railings/slab/approach for Bridges	S/SRI/U
Road Furniture	
Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
Compliance History	
Status of ATR's & any others	

Rating :

Satisfactory (S)	11/1
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

11.1.21
J. E.

11/1
(Signature)