

FIELD INSPECTION REPORT

Date of Inspection :	04.01.2021	District:	Ayodhya
Division :	Bara Div. Ayodhya	Length (km):	0.750 km
Name of the Road:	To 6 to Mangusads		
Scheme/Programme:	MAINTENANCE		
Package No.:	BR-02R-581	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance ✓		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameter to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U S.
b)	Condition of Surfacing	S/U S
c)	Riding Quality	S/U S
d)	Road Camber	S/U S.
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No S.
f)	Contraction Joints provided or not (CC Pavement)	Yes/No S.
g)	Compaction of flank/slope & raincuts if any	Yes/No S.
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U S.
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U —
c)	Condition of railings/slab/approach for Bridges	S/SRI/U —
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No Yes
4.	Compliance History	
a)	Status of ATR's & any others.	

Overall Rating :

Satisfactory (S)	"S"
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

04-01-2021
JRE

04.01.2021
AB Barua (Signature)

NAME: