

Division:	Bellary	Length (km):	2.024 K.M.
Name of the Road:	Lisy. Pussu to Bin-toli N. Road		
Scheme/Programme:	MAINTENANCE		
Package No.:	BR. 37R-387	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance UNDER Maint		
Work is a case of:	New Connectivity/Up gradation/ Maintenance Maint.		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	yes
f)	Contraction Joints provided or not (CC Pavement)	yes
g)	Compaction of flank/slope & raincuts if any	yes
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	yes
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N/A
c)	Condition of railings/slab/approach for Bridges	N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	yes
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Am
29.12.2020
(Signature)

NAME: SUNIL KUNAR