


# FIELD INSPECTION REPORT

Date of Inspection: 11/01/21		District: Samastipur
Division: RWD Dalsinghsarai		Length(km): 0.550
Name of Road : L025 to Pasi Tola		
Scheme / Programme:		MAINTENANCE
Package No:		Road Id No: GTSNYS
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of:		New Connectivity/ Up gradation/ Maintenance
Sl. No	Parameters to be Checked	Remarks
<b>1</b>	<b>Pavement</b>	
a)	Road Junction Condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	S
f)	Constraction Joint provided or not(CC Pavement)	S
g)	Compaction of flank/slope & raincuts if any	U
<b>2</b>	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls , Slab in RCC culverts	-
c)	Condition of railings/slab/approach for Bridge	-
<b>3</b>	<b>Road Furniture</b>	
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	SRI
<b>4</b>	<b>Compliance History</b>	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory(S)	
Satisfactory but requires Improvement(SRI)	SRI
Unsatisfactory(U)	

  
 11/01/21  
 (Signature)

NAME: Deepak Chandra Sinha  
 DESIGNATION: S.E.