

FIELD INSPECTION REPORT

Date of Inspection: 12/12/2020		District: Bidar
Division: Maharashtra	Length(km): 0.600	
Name of the Road: Lakshabiganj Prakhond Close to Pakri Vithal Talga		
Scheme/Programme: MAINTENANCE		
Package No. GITSNY	Road Id No:	
Status Of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up Gradation/Maintenance		
SL.No.	Parameter to be checked	Remarks
1	Pavement	
a)	Road Junction Condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavements	Yes/No
f)	Contraction joints provided or not(CC Pavements)	Yes/No
g)	Compaction of flank/slope&rain cuts if any	Yes/No
2	Cross Drainage	
a)	Condition of Head wall in Hume Pipe culverts including its painting	S/SRI/U
b)	Condition of abutment & wing wall, slab in RCC Culvert	S/SRI/U
c)	Condition of Railings/slab/approach for bridges	S/SRI/U
3	Road Furniture	
a)	Whether Sign boards/informatory/Cautionary board/K.M& 200' mtr.stones/Pavements Road markings are provided and maintained	Yes/No
4	Compliance History	
a)	Status Of ATR,s & any others	N/A

Overall Rating

Satisfactory(S)	U
Satisfactory but requires Improvement (SRI)	
Unsatisfactory(U)	

Ajit Kumar
NAME:
Designation

Ajit Kumar
(Signature) 12/12/2020