

FIELD INSPECTION REPORT

Date of Inspection : 09.01.2021	District: BANKA
Division : RWD BANKA-2	Length (km): 0.514
Name of the Road: Nawada Goradiah Road to Makraundha (NABARD)	
Scheme/Programme:	MAINTENANCE ✓
Package No.:	Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance ✓ (2nd year)
Work is a case of:	New Connectivity/Up gradation/ Maintenance (2nd year)

SL No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

[Signature]
09.01.2021
(Signature)

NAME:

Rajendra Kumar

DESIGNATION:

J.E

FIELD INSPECTION REPORT

Date of Inspection : 09.01.2021	District: BANKA
Division : RWD, BANKA-2	Length (km): 1.103
Name of the Road: Hawada Goradiah Path To hartada (MMGLY, GEN)	
Scheme/Programme:	MAINTENANCE ✓
Package No.:	Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance ✓
Work is a case of:	New Connectivity/Up gradation/ Maintenance ✓ 5th year

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

NAME: — Rajendra Kumar

DESIGNATION: — S.E

09.01.2021
(Signature)

FIELD INSPECTION REPORT

Date of Inspection : 09.01.2021	District: BANKA
Division : RWD BANKA-2	Length (km): 1.779
Name of the Road: LO24 To Malahi (PMHR), PK4-BR-03R-333	
Scheme/Programme:	MAINTENANCE
Package No.: BR-03R-333	Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance ✓
Work is a case of:	New Connectivity/Up gradation/ Maintenance, 4th year

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

09.01.2021
(Signature)

NAME: - Rajendra Kumar
DESIGNATION: S.E.

FIELD INSPECTION REPORT

Date of Inspection : 09.01.2021	District: BANKA
Division : RWD BANKA-2	Length (km): 0.948
Name of the Road: Kotwali Gopalpur Road to Gobindpur (N.M. 64, S.C.)	
Scheme/Programme:	MAINTENANCE ✓
Package No.:	Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance ✓
Work is a case of:	New Connectivity/Up gradation/ Maintenance, 5th year

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

[Signature]
(Signature)

NAME: — Rajendra Yadav

DESIGNATION: — J.E