


FIELD INSPECTION REPORT

Date of Inspection: → 11/12/2020		District: Siwan
Division: Maharajganj	Length(km)	
Name of the Road: Lakshmaya Tola to Baghiya Kanchi Tola		
Scheme/Programme: MAINTENANCE		
Package No. GTSNY	Road Id No:	
Status Of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up Gradation/Maintenance		
SL.No.	Parameter to be checked	Remarks
1	Pavement	
a)	Road Junction Condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavements.	✓ Yes/No
f)	Contraction joints provided or not(CC Pavements)	✓ Yes/No
g)	Compaction of flank/slope & rain cuts if any	✓ Yes/No
2	Cross Drainage	
a)	Condition of Head wall in Hume Pipe culverts including its painting	✓ S/SRI/U
b)	Condition of abutment & wing wall, slab in RCC Culvert	✓ S/SRI/U
c)	Condition of Railings/slab/approach for bridges	✓ S/SRI/U
3	Road Furniture	
a)	Whether Sign boards/informatory/Cautionary board/K.M & 200 mtr. stones/Pavements Road markings are provided and maintained	✓ Yes/No
4	Compliance History	
a)	Status Of ATR,s & any others	n/a

Overall Rating

Satisfactory(S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory(U)	


 NAME: A.P. Kumar
 Designation: JE


 (Signature)