

FIELD INSPECTION REPORT

Date of Inspection : 9.01.2021

Division : Condu

District : GAYAN

Name of the Road : Jurei Jola

Length (km): 0.500 K.M.

Scheme/Programme: MAINTENANCE

Under Construction

Package No.:

Road Id No.:

Status of the Project:

Ongoing/Completed Under Maintenance

Work is a case of:

New Connectivity/Up gradation/ Maintenance

Sl. No.

Parameters to be checked

Remarks

1.

Pavement

a)

Road Junction condition

b)

Condition of Surfacing

✓S/U

c)

Riding Quality

✓S/U

d)

Road Camber

✓S/U

e)

Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.

✓S/U

f)

Contraction Joints provided or not (CC Pavement)

✓Yes/No

g)

Compaction of flank/slope & raincuts if any

✓Yes/No

2.

Cross Drainage

a)

Condition of head walls in Hume pipe culverts including its painting

✓S/SRI/U

b)

Condition of Abutment & Wing walls, Slab in RCC culverts

S/SRI/U

c)

Condition of railings/slab/approach for Bridges

S/SRI/U

3.

Road Furniture

a)

Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained

✓Yes/No

4.

Compliance History

a)

Status of ATR's & any others

NO

Overall Rating :

Satisfactory (S)	✓S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: Kani Rm

DESIGNATION: J-2