FIELD INSPECTION REPORT

Date of Insp	ection:	2/1/2021	District:	Patra	
Division: Danabur Length (km): 1.2 K				m	
Name of the	Road:	vishnapur (Tola se	Dhnase	chaki-
Scheme/Pro	gramme:	MAINTENANCE			
Package No.			Road Id No.:		
Status of the		Ongoing/Completed	4.71		
Work is a ca	ise of:	New Connectivity/U		rtenance	EUGNICENHARIANI, YH
Sl. No.		Parameters to	be checked		Remarks
1. Pa	vement-				
a) Ro	Road Junction condition				S/ U
b) Co	Condition of Surfacing				S/ U
c) Rie	Riding Quality				SÆ
d) Ro	Road Camber				SA
e) $\begin{bmatrix} W_1 \\ ag \end{bmatrix}$	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.				Yes/No-
f) Co	Contraction Joints provided or not (CC Pavement)				Yes/No-
g) Co	Compaction of flank/slope & raincuts if any				
. 2 Cı	ross Draina	ge in a light	Part of the control o		
a) Co	Condition of head walls in Hume pipe culverts including its painting				S/SRI/U
b) Co	Condition of Abutment & Wing walls, Slab in RCC culverts				S/SRI/U
c) Co	Condition of railings/slab/approach for Bridges				S/SRI/U
3. R	oad Furniti	ire	ACTION OF		
a) W	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				Yes/ No
4, Co	Compliance History.				
a) Sta	atus of ATR	s & any others		The second section with the second section second	NO

Overall Rating

Satisfactory (S)

Satisfactory but requires Improvement (SRI) SRT

Unsatisfactory (U)

12/1/2021 JE Bilda

(Signature)

NAME:

DESIGNATION: