

FIELD INSPECTION REPORT

Date of Inspection:	08.01.21	District:	Aurangabad
Division:	North Dist. Aurangabad	Length (km):	0.505 Km.
Name of the Road:	To, to M/4 K/260		
Scheme/Programme:	MAINTENANCE		
Package No.:	BR-02R-65E	Road ID No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	SAU S
b)	Condition of Surfacing	SAU S
c)	Riding Quality	SAU S
d)	Road Camber	SAU S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No S
f)	Contraction Joints provided or not (CC Pavement)	Yes/No S
g)	Compaction of flank/slope & raincuts if any	Yes/No S
2.	Clear Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U -
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U -
c)	Condition of railings/slab/approach for Bridges	S/SRI/U -
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No -
4.	Compliance History	
a)	Status of ATR's & any others	Maintenance board not available & lane road not painted, 200m to slope not maintained

Overall Rating

Satisfactory (S)	☒
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Ranjan
08.01.21
2E

08.01.21
Ata Barua
(Signature)

NAME: