## FIELD INSPECTION REPORT

Date of Inspection: 14-141/2021			District:	RAHTAS	
Division: SASARAM-2			Length (km):	2.36 m	
Name of	the Road: RAG	PUR BEMGA	GAR KIAD TO RAMYOR	H BATHAN	
	Programme:	MAINTENANC			
Package	No.:	Land of the state	Road Id No.:		
-	f the Project:	CONTRACTOR OF THE PROPERTY AND ADDRESS OF THE PARTY OF TH	ted/Under Maintenance		
Work is	a case of:	New Connectivit	y/Up gradation/ Maintenance	-	
Sl. No.		Parameters	to be checked	Remarks	
1.	Pavement	The state of the s		European Constitution (Constitution of the Constitution of the Con	
a)	Road Junction condition			SAU	
b)	Condition of Surfacing			US/U	
e)	Riding Quality			SU	
d)	Road Camber			SA	
e)	Whether free aggregates in c	sed Yes/No			
f)	Contraction Joints provided or not (CC Pavement)			Yes4No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			ting S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			0m Yes/No	
4.	Compliance History			+ATR.	
a)	Status of ATR's & any others ATR Submitted to			y to H. C.	

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Models 14/01/2021 (Signature)

NAME: BYBHERDAR NUMBER