

FIELD INSPECTION REPORT

Date of Inspection:	09/11/2021	District:	NALANDA
Division:	1115A	Length (km):	1.160 km
Name of the Road:	Bikar - Rasulpur Rd. to Bharanpur (Bihar)		
Scheme/Programme:	MAINTENANCE	Road Id No.	
Package No.:	M&C 54	Status of the Project:	Ongoing/Completed/Under Maint. since ✓
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked		
1.	Pavement		
a)	Road Junction condition		S
b)	Condition of Surfacing		S
c)	Riding Quality		S
d)	Road Camber		S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement		YES/NO
f)	Contraction Joints provided or not (CC Pavement)		YES/NO
g)	Compaction of flank slope & talcups if any		YES/NO
2.	Cross Drainage		
a)	Condition of head walls in culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		N/A S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 100m stones/Pavement road markings are provided and maintained		YES/NO
4.	Compliance History		
a)	Status of ATR's & any others		N/A

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	-

ANJANE KUMAR
NAME

(Sign) 09/11/21