

FIELD INSPECTION REPORT

Date of Inspection : 09/11/2021	District: NALANDA
Division : H/LSA	Length (km): 1.490 km
Name of the Road: Ehangar-Bihar Panchayath Rd to Bhagwan high, Sudehdeo high Path	
Scheme/Programme: MAINTENANCE	
Package No.: MATGSY	Road Id No.
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/Maintenance	

Sl. No.	Parameters to be checked	Rating
1.	Pavement	
a)	Road Junction condition	U
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	YES/NO
f)	Construction Joints provided or not (CC Pavement)	YES/NO
g)	Condition of Bank slope & inlets if any to be cleaned	YES/NO
2.	Cross Drainage	
a)	Condition of head walls in lime pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	-N/A- S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/lan & 100m stones/Pavement road markings are provided and maintained	YES/NO a few missing Main board not found
4.	Compliance History	
a)	Status of ATR's & any others	— NO —

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	—

ANAND KUMAR
NAME:

(Signature)
09/11/21