FIELD INSPECTION REPORT

Date of Inspection:	>10/12/2020	District: - Si Jen		
Division: Mahar	algani	Length (km): 100 KM		
Name of the Road: lekhrawa to Dusach Tolg				
Scheme/Programme:	MAINTENANCE	M MGSY NDB		
Package No.:	Value	Road Id No.:		
Status of the Project:	Ongoing/Completed/Under Maintenance			
Work is a case of:	New Connectivity/Up gradation/ Maintenance			

Sl. No.	Parameters to be checked	Remark	
1.	Pavement		
a)	Road Junction condition	SAU	
b)	Condition of Surfacing		
c)	Riding Quality		
d)	Road Camber	\\$/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		
c)	Condition of railings/slab/approach for Bridges		
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		
4.	Compliance History		
	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	(2)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

Ajit Kumal JE NAME: