

FIELD INSPECTION REPORT

Date of Inspection:	06-01-2021	District:	Aurangabad
Division:	W&D Div. Aurangabad	Length (km):	1.15 km
Name of the Road:	Rampur - Pithundiy to Banka Bigha -		
Scheme/Programme:	MAINTENANCE		
Package No.:	BR-02R-741	Read Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/S S
b)	Condition of Surfacing	S/S S
c)	Riding Quality	S/S S
d)	Road Camber	S/S S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No Yes
f)	Contraction Joints provided or not (CC Pavement)	Yes/No Yes
g)	Compaction of flank/slope & raincuts if any	Yes/No Yes
2.	Cross Drainage	
a)	Condition of head walls in Flume pipe culverts including its painting	S/S/PU S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/S/PU -
c)	Condition of railings/slab/approach for Bridges	S/S/PU -
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	100m Yes/No Yes
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating

Satisfactory (S)	"S"
Satisfactory but requires Improvement (S.R)	
Unsatisfactory (U)	

Rating
06-01-20
J.E.

NAME:

06-01-2021
A. B. B. (Signature)