

FIELD INSPECTION REPORT

Date of Inspection:	07.01.2021	District:	Aurangabad
Division:	North Aurangabad	Length (km):	0.600 km
Name of the Road:	To Kadiapada via Mangurahi.		
Scheme/Programme:	MAINTENANCE		
Package No.:	BR-02R-742	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance ☒		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/S ☒
b)	Condition of Surfacing	S/S ☒
c)	Riding Quality	S/S ☒
d)	Road Camber	S/S ☒
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ☒
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ☒
g)	Compaction of flank/slope & raincuts if any	Yes/No ☒
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/S ☒
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/S ☒
c)	Condition of railings/slab/approach for Bridges	S/S ☒
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 100m stones/Pavement road markings are provided and maintained	Yes/No ☒
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	☒
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Rating
07.01.21
J2

NAME:

07.01.2021
AB. Basu (Signature)