

FIELD INSPECTION REPORT

Date of Inspection:	08.01.21	District:	Muzaffargarh
Division:	North West Frontier	Length (km):	9.00 km
Name of the Road:	T-66 to Kullian to Sahayana		
Scheme/Programme:	MAINTENANCE		
Package No.:	BR-02R-746	Road ID No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sr No.:	Inspection to be made at	Remarks	
1.	Pavement		
a)	Road Junction condition	S/U	S
b)	Condition of Surfacing	S/U	S
c)	Riding Quality	S/U	S
d)	Road Camber	S/U	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	Yes
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	Yes
g)	Compaction of flank/slope & raincuts if any	Yes/No	Yes
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SR/U	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SR/U	-
c)	Condition of railings/slab/approach for Bridges	S/SR/U	-
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m Yes/No	Yes
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating

Satisfactory (S)	"S"
Satisfactory but requires Improvement (SR)	
Unsatisfactory (U)	

Review
08.01.2021
ZE

Signature
08.01.21
AB, Batur

NAME: