

FIELD INSPECTION REPORT

Date of Inspection : 12.12.2020	District: N. Champaran
Division : Belthari	Length (km): 1.40 km
Name of the Road: Lal Sariga Panchayat Bharonce Refuge Colony	
Scheme/Programme:	MAINTENANCE
Package No.: NAWARD	Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance UNDER Maint
Work is a case of:	New Connectivity/Up gradation/ Maintenance New Connectivity

Sl.No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S L/S/U
b)	Condition of Surfacing	S -S/U
c)	Riding Quality	S L/S/U
d)	Road Camber	S L/S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N/A L/Yes/No
f)	Contraction Joints provided or not (CC Pavement)	N/A Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes L/Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N/A S/SRI/U
c)	Condition of railings/slab/approach for Bridges	N/A S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	L/Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	(S)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	


12.12.2020
(Signature)

NAME: SUNIL KUNAR

DESIGNATION: J.E