MMGSY (SC) FIELD INSPECTION REPORT

Date of	Inspection: @	03-01-21	District:	
Divisio			Length (km): 3.500 K·m	
Name	f the Road: Cl	ritauni more	to Chitauni Gram(Village)
Scheme	Programme:	MAINTENANCE		
Packag		./	Road Id No.:	
Status of the Project: Ongoing/Completed/Under Maintenance Work is a case of: New Connectivity/Up gradation/ Maintenance				
	1			
SI. No.	Parameters to be checked		Remarks	
1.	Pavement			
a)	Road Junction condition			S/U
b)	Condition of Surfacing			S/U
c)	Riding Quality			S/U
d)	Road Camber			S/U
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2	Cross Draining	6		
a)	Condition of head walls in Hume pipe culverts including its painting S/SR			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges S			S/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained Yes/No			Yes/No
4.	Compliance H	stoky		
-	A STATE OF THE PARTY OF THE PAR	THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS NAMED IN COLUMN TW		No. of the second second

Overall Rating

Status of ATR's & any others

Satisfactory (S)	Norkintro
Satisfactory but requires Improvement (SRI)	1
Unsatisfactory (U)	

(Signature)

NAME: A. Alcom

DESIGNATION: J.E.