## FIELD INSPECTION REPORT

Date of Inspection:  3 61 21			District: Patn		
			Length (km): Jol		and the second s
Name of the Road: Origano Domkhana Se Nadwar origana Road Scheme/Programme: MAINTENANCE 11+7454(se) or going (E w sto					
Scheme/Programme: MAINTENANCE 11-7454(Se)   On gaing (E w st					
Package No.:		Road Id No.:		<u> </u>	
Status of the Project: Ongoing/Completed/Under Maintenance					1
Work is a case of: New Connectivity/Up gradation/ Maintenance					
SI. No.		Parameters to I	jechecked		Remarks
1.	Pavement				
a)	Road Junction condition				S/U
b)	Condition of Surfacing				S/U
e)	Riding Quality				S/U
d)	Road Camber				S/U
e)	Whether free from defects such as visible cracks, exposed Yes/No aggregates in case of CC Pavement.				
ſ)	Contraction Joints provided or not (CC Pavement)				Yes/No
g) .	Compaction of flank/slope & raincuts if any				Yes/No
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting				S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts				S/SRI/U
c)	Condition of railings/slab/approach for Bridges				S/SRI/U
3,	Road Eurniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				Yes/No
4,	Compliance History				1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
a)	Status of ATR's	& any others			NO ATIZ
Overall Rating :					
Satisfactory (S)					S
Satisfactory but requires Improvement (\$RI)				(IS	_
Unsatisfactory (U)					
- E   w started					
Purkar Prasad					3/1/21
Pusikar Prosad Aut. Engèneu (Signat					ature)
NAME:	ζ.	•			