

FIELD INSPECTION REPORT

Date of Inspection:	07.01.2021	District:	Aurangabad
Division:	Muzir Aurangabad	Length (km):	01.243 Km
Name of the Road:	Piston-Rasulpur Path to Rakshani na Palangani		
Scheme/Programme:	MAINTENANCE		
Package No.:	BR-02R-452	Road ID No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameter to be checked	Remarks	
1. Pavement			
a)	Road Junction condition	SA	S
b)	Condition of Surfacing	S/U	S
c)	Riding Quality	SA	S
d)	Road Camber	SA	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	Yes
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	Yes
g)	Compaction of flank/slope & raincuts if any	Yes/No	Yes
2. Cross-Drainage			
a)	Condition of head walls in flume pipe culverts including its painting	S/SRI	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI	-
c)	Condition of railings/slab/approach for Bridges	S/SRI	-
3. Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 100m stones/Pavement road markings are provided and maintained	Yes/No	Yes
4. Compliance History			
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	15
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Ranjan
07.01.21
J.E.

07.01.2021
A. B. Bhowmik

NAME: