

ROAD CONDITION SURVEY

Date of Inspection	07/01/2021	Inspector	Prasanna
Location	on Highway	Length (km)	0.802
Name of the Road	on Highway	State	Andhra Pradesh
Stationing	MAINTENANCE		
Project No.	MAINT-112	Road ID No.	
Source of the Data	Original	Compliance	Under Maintenance
Work is a part of	New Construction	Up gradation	Maintenance

Road Condition			
a)	Road Surface condition	SL	S
b)	Condition of Surfacing	SL	S
c)	Grading Quality	SL	S
d)	Road Curb	SL	S
e)	Whether free from defects such as visible cracks, dips and aggregates in case of CC Pavement.	Yes	Yes
f)	Construction joints provided or not (CC Pavement)	Yes	Yes
g)	Compaction of Backfills & subgrade if any	Yes	Yes
Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its parting	SL	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	SL	U
c)	Condition of railings/slab/approach for Bridges	SL	U
Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	Yes	Yes
Compliance History			
a)	Status of ATR's & any others		

Overall Rating

Satisfactory (S)	"S"
Satisfactory but requires Improvement (S I)	
Unsatisfactory (U)	

Raj
07.01.21
JB

NAME:

07/01/2021
A. S. Rao (Sign)