

134
345

FIELD INSPECTION REPORT

Manghi

Date of Inspection :	03/01/21	District:	Saran
Division :	Chhapara-2	Length (km):	2.9 Km
Name of the Road:	Balesara to Samtapani		
Scheme/Programme:	MAINTENANCE	M. G. S. A.	Kanjakurain
Package No.:		Road Id No.:	31306302004
Status of the Project:	Ongoing Completed Under Maintenance	work Not started	
Work is a case of:	New Connectivity Up gradation Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S/U	
b)	Condition of Surfacing	S/U	
c)	Riding Quality	S/U	
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

work Not started

Unsatisfactory.


 03/01/21
 (Signature)

NAME: Chandravir Narayan

DESIGNATION: P. A. (Ex. Er)