

74/53

FIELD INSPECTION REPORT

Iswarpur

Date of Inspection : 26/12/20	District: Saran
Division : Chhapra-2	Length (km): - 8 km
Name of the Road: Repair of road from Iswarpur to Gopendpur Newari	(Remaining part of 9 km up to Newari)
Scheme/Programme: MAINTENANCE	MR-3054 (old)
Package No.:	Road Id No.: 91306308067
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

S

Some part of Road is damaged due to flood. Some part has been washed away. Brick Batt has been filled in cutting portion. Now Road is motarable in cutting portion.

Satisfactory

26/12/20
(Signature)

NAME:

DESIGNATION: