

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- Gyan Dibhakar

(Naigak)

2 Name of Block/Road :- Janta kanta to matnaje road

(A) For Road:

1. Damage Location/Chainage :- 0.550 km, 0.700 km, 0.900 km, 2.20 km, 2.80 km
2. Damage Length :- 0.310 km 3.0 km, 3.20 km, 3.50 km
3. Nature of Damage :-
4. Details of Restoration Works :- (Length 10.30 km)
 - (i) Material being used in Restoration works:- Brck bats.
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :- 0.310 km

(B) For Bridge:

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:-
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :-

Signature of JE/AE/EE


24.12.20

Signature

(Name of Inspection)

EE
RWD work Division
muzaffarpur East-1

GENERAL ABSTRACT

Name of Road Janta kata to Motnaje Road

District Muzaffarpur

Block Gaighat

Division Muzaffarpur East-2

Length of Road (in Km) 10.300 Km

SI. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	20.889
2	Sand Filling	0.000
3	Sand bag	0.000
4	H.P.	0.261
	GRAND SUB TOTAL	21.150
	TOTAL COST OF PROJECT IN LACS =	21.150

Rs. 21.15 Lac

Signature
20/11/2020
JE
PWD

K.K.T
20/11/2020
AE
PWD

Signature
EE
PWD

Technically Approved for Rs. 21.15 Lac.
(Rupees twenty one lac, fifteen thousand only)

Signature
4/1/21
SE
PWD work circle
muzaffarpur