

## Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- *Gyan Bhakti*

2 Name of Block/Road :- *Lo39-Bela Gobilo to Bakri (Naigad)*

### (A) For Road: ✓

1. Damage Location/Chainage :- 0.8050km, 0.100km, 0.200km, 0.350, 0.550km  
(Length = 1.524km)
2. Damage Length :- 0.137km
3. Nature of Damage :-
4. Details of Restoration Works :-
  - (i) Material being used in Restoration works:- *Brick bats*
  - (ii) Equipment's/Tools being used in Restoration works:-
  - (iii) Procedure taken up in Restoration works:-
  - (iv) Restored Length :- 0.137 km

### (B) For Bridge:

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
  - (i) Material being used in Restoration works:-
  - (ii) Equipment's/Tools being used in Restoration works:-
  - (iii) Procedure taken up in Restoration works:-
  - (iv) Restored Length :-

Signature of JE/AE/EE



Signature

(Name of Inspection)

*EE  
RWD work Division  
muzaffarpur East L*

## GENERAL ABSTRACT

Name of Road L039-Bela Gopi L041 to Bakhri (VR53)

District Muzaffarpur

Block Gaighat

Division Muzaffarpur East-2

Length of Road (in Km) 2.300 Km

| SI. No. | DESCRIPTION                            | AMOUNT (LAKHS) |
|---------|--|----------------|
| 1       | Jhama metal                            | 1.524          |
| 2       | Sand Filling                           | 0.000          |
| 3       | Sand bag                               | 0.000          |
| 4       | Bamboo Piles                           | 0.000          |
|         | <b>GRAND SUB TOTAL</b>                 | <b>1.524</b>   |
|         | <b>TOTAL COST OF PROJECT IN LACS =</b> | <b>1.524</b>   |

Says 1.52 lac

9  
20/12/20  
JE  
RWD

1.52  
20/12/20  
AE  
RWD

Open  
20/12/20  
EE  
RWD

Technically Approved for Rs 1.52 lac.  
(Rupees one lac, fifty two thousand only.)

10  
4.1.21  
SE  
PWD work circle  
muzaffarpur