

## Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- Gyan vibhakar

2 Name of Block/Road :- PWD sarak to satghata malla foli (Naigat)

(A) For Road: ✓

1. Damage Location/Chainage :- 0.300 km, 0.70km, 0.90km, 1.50km, 1.80km, 2.20km
2. Damage Length :- 522.18 m (0.52218 km) (Length = 2.32 km)
3. Nature of Damage :-
4. Details of Restoration Works :-
  - (i) Material being used in Restoration works:- brick bats
  - (ii) Equipment's/Tools being used in Restoration works:-
  - (iii) Procedure taken up in Restoration works:-
  - (iv) Restored Length :- 0.522 km. (0.52218 km)

(B) For Bridge: ✗

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
  - (i) Material being used in Restoration works:-
  - (ii) Equipment's/Tools being used in Restoration works:-
  - (iii) Procedure taken up in Restoration works:-
  - (iv) Restored Length :-

Signature of JE/AE/EE

  
Signature

(Name of Inspection)

EE  
PWD WORK DIVISION  
Muzaffarpur East-1

### GENERAL ABSTRACT


Name of Road PWD Sarak to Satghata malah tola  
 District Muzaffarpur  
 Block Gaighat  
 Division Muzaffarpur East-2  
 Length of Road (in Km) 2.327 Km

SI. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	15.429
2	Sand Filling	0.000
3	Sand bag	0.000
4	Bamboo Piles	0.140
	<b>GRAND SUB TOTAL</b>	<b>15.569</b>
	<b>TOTAL COST OF PROJECT IN LACS =</b>	<b>15.569</b>


Says 15.57 lac

  
 JE  
 RWD

  
 AE  
 RWD

  
 RWD

Technically Approved for Rs 15.57 lac  
 (Rupees fifteen lac fifty seven thousand only)

  
 SE  
 RWD work circle  
 muzaffarpur