

Inspection Report for Flood Damage Work

Date.:

1. Name of PIUs – Executive Engineer, R.W.D., Works, Division, Muzaffarpur West

2. Name of Block – Kanti

3. Name of Road/Bridge – Mithan Sarai Pusakalaya Ram Sevak shah ke ghar ke pas Mukhya Sadak to Jamalabad REO path tak via Gandak Bandh Aur Ramsomari Devi ke ghar hote hue

A. for Road

1. Damage Location/Chainage : 0.670 km

2. Damage Length : 101.00 m

3. Nature of Damage :

4. Details of Restoration Works :

i. Material being used in Restoration works : - Brick's Ball, Local sand

ii. Equipments/Tools being used in Restoration Works : Tractor, Roller, JCB

iii. Procedure taken up in Restoration works :

iv. Restored Length : - 101.00 m

B. for Bridge

1. Damage Location/Chainage : N/A

2. Damage Length : N/A

3. Nature of Damage :

4. Details of Restoration Works :

i. Material being used in Restoration works :

ii. Equipments/Tools being used in Restoration Works :


iii. Procedure taken up in Restoration works :

iv. Restored Length :


J.E.


A.E.


Executive Engineer,
R.W.D. Works Division,
Muzaffarpur west


Signature
(Name of Inspector)

GENERAL ABSTRACT

Name of Road Mithan sarai Puskalays Ram Sewak Sah ke Ghar Ke Pass Mukh Sadak to Jomalobod REO Path
 District Tak Via Gandak Bandh or Ramsomari Devi Ke Ghar Hote Huye
 Block Muzaffarpur
 Division Kanti
 Length of Road (in Km) Muzaffarpur West 1.100 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Earthwork	0.000
1	Jhama metal	3.808
2	Sand Filling	0.276
3	Sand Bag	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	4.084
TOTAL COST OF PROJECT IN LACS =		4.084

[Signature]
 JE
 RWD

[Signature]
 AE
 RWD

[Signature]
 EE
 RWD

Technically approved for Rs: 4.084 lacs (Rupees four lacs eight thousand four hundred) only.

[Signature]
 31/12/20
 Superintending Engineer
 Rural Works Department
 Work Circle Muzaffarpur
[Signature]
 13/12/20
 J.E.

Sl. No.	SDB SL NO	MORD Ref. No	Description	Unit	QUANTITY	RATE	AMOUNT (in Rs.)
1		13.7 SoR Bihar Govt. (1985)	Jhama metal Labour for consolidation in Jhama metal by Road Roller in proper grade camber and super elevation dry and wet rolling including cost of running charge of roller diver and khalasi making and maintaining diversion light barrier - do - do- danger signal etc. all complete .				
			Appendix - I	Cum	187.29		
				Total	187.29	2033.34	380824.25
			Sand Filling				
2		11.20	Fillling in foundation trenches as per drawing and technical specification Clause 305.3.9				
			Appendix - II	Cum	60.650		
				Total	60.65	454.53	27567.24
						SUB TOTAL =	408391.49

Bo1
07/12/2020
df

11802/11/11/2020