

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- Gyan vibhakar

2 Name of Block/Road :- Sakarwara shoor pmaey path to kothia thel (straight)

(A) For Road: ✓

1. Damage Location/Chainage :- 0.600 km, 0.850 km, 1.50 km, 1.70 km, 1.90 km
(Length = 5.525 km)
2. Damage Length :- 283.65 m (0.28365 km).
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:- Brick bats.
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :- 0.283 km (0.28365 km)

✗ (B) For Bridge:

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:-
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :-

Signature of JE/AE/EE


16.12.20
Signature

(Name of Inspection)

CE
PWD work Division
muzaffarpur (East-1)

GENERAL ABSTRACT

Name of Road Sakarwars S Noor PMGSY Path to Kothia Thel (Sakarwara Sawik Bhag-2)

District Muzaffarpur

Block Gaighat

Division Muzaffarpur East-2

Length of Road (in Km) 2.800 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	5.525
2	Sand Filling	0.000
3	Sand bag	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	5.525
TOTAL COST OF PROJECT IN LACS =		5.525

Sum 5.53 lac

Am 31/12/20
JE
RWD

Am 31/12/20
AE
RWD

Am 31/12/20
EE
RWD

Technically Approved for Rs 5.53 lac.
(rupees five lac fifty three thousand only).

Am 31/12/20
SE
PWD works circle
muzaffarpur.