

FIELD INSPECTION REPORT

Date of Inspection:	14/01/2021	District:	Sheikhpura
Division:	Sheikhpura	Length (km):	1.745 km.
Name of the Road:	Bairbhga Mahua Road to Purb Tola Bhadarthi		
Scheme/Programme:	MAINTENANCE	MMGSY (S) Under Eys. Maint	
Package No.:	Road Id No:		
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/Maintenance		

Sl. No.	Parameters to be checked	Remarks
1	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4	Compliance History	
a)	Status of ATR's & any others	—

Raincuts at and edge cutting of road found at some places

Informative board, 200 m stone km stone not maintained properly.

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	—

SAN
14/01/2021
(Signature)

NAME: SANGRAM HEMBRAM

DESIGNATION: A.E.