

FIELD INSPECTION REPORT

Date of Inspection : 16-12-20	District: Gopalganj
Division : R.W.D. Gopalganj-1	Length (km): 2.60
Name of the Road: NH-28 to Bathua Hrizna Tola	
Scheme/Programme:	MAINTENANCE
Package No.:	Road Id No.: ✓
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U (S) ✓
b)	Condition of Surfacing	S/U (U) ✓
c)	Riding Quality	S/U (U) ✓
d)	Road Camber	S/U (S) ✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No Yes ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No Yes ✓
g)	Compaction of flank/slope & raincuts if any	Yes/No Yes ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U (U) ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No No
4.	Compliance History	
a)	Status of ATR's & any others	No ATR

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	(U)

NAME:

DESIGNATION:

16-12-20
J-E

16.12.2020
BE

APP -
16/12/2020
(Signature)