

FIELD INSPECTION REPORT

Date of Inspection :		District: <i>Sitamarhi</i>
Division : <i>Belahat</i>		Length (km): <i>2.85</i> to <i>6.84</i>
Name of the Road: <i>Bhaswan Ghat to maulanagar Dist Tola</i>		
Scheme/Programme:		MAINTENANCE <i>PMGSY</i>
Package No.:		Road Id No.:
Status of the Project:		Ongoing/Completed/Under Maintenance
Work is a case of:		New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓ S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	Yes

Overall Rating :

Satisfactory (S)	✓
Satisfactory but requires Improvement (SRI)	x
Unsatisfactory (U)	x

G. S. H.
11.1.21
 (Signature)

NAME: *Girish Prasad Sah*

DESIGNATION: *J. E., RWD, Belahat*