FIELD INSPECTION REPORT

Da	te of Inspection: //-/- 21	District: East clamps	yay	
	ivision: Revaul Length (km): 1.57/ ame of the Road: To1 to Parties Tola via Hajma T			
Na	me of the Road: To/ to	Partiya Tola VIA Hayma 7	ola	
Sch	eme/Programme: MAINTE	LANCE MACS Y/SO		
Pac	Package No.: Road Id No.: 3170 8313013			
	ntus of the Project: Ongoing/Completed/Under Maintenance		gran in a seek property of the second property of the second	
Wor	ork is a case of: New Connectivity/Up gradation/ Maintenance			
Si.1	No. Paran	neters to be checked	Remarks	
1.	Pavement		and the same of th	
a)	a) Road Junction condition		1 5/U	
b)	b) Condition of Surfacing		\$/0	
c)	Riding Quality		SIU	
d)			S /U	
c)		ts such as visible cracks, exposed vement.	Yes/No	
ſ)	Contraction Joints provided or not (CC Pavement)		Yes/No	
g)	Compaction of flank/slope & raincuts if any Yes/No		Yes/No	
2.	2. Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting S/SRI/U		✓S/SRI/U	
	Condition of Abutment & Wing walls, Slab in RCC culverts 1, 5/5/8/1/		4.5/5/0/0	
c)	Condition of railings/slab/approach for Bridges 14 - S/SRI/U		4·S/SRI/U	
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Ycs/No	
4.	Compliance History		M.A.	
1)	Status of ATR's & any others			
A	A STATE OF THE STA)	

Overall Rating :

(8)
Satisfactory (S)
Satisfactory but requires Improvement (SRI)
Unsatisfactory (U)

NAME: Witholish Kumar Singl DESIGNATION: Junior Eginear, Ravaul