FIELD INSPECTION REPORT

Date of	Inspection :	15-12-20	District: West- Cha	mparan	1	
Division: Bettian Length (km):						
Name of the Road: To1 to Bin toli						
Scheme/Programme: MAINTENANCE PM LLY						
Package No.: Road Id No.:					1.	
	f the Project:	Ongoing/Completed/Under Maintenance Vuler Main			fainance	
Work is a case of: New Connectivity/Up gradation/ Maintenance						
8500	Parameters to the checked , Remarks					
4	Pinament					
a)	Road Junction	√S/U				
b)	Condition of Surfacing			√s/U		
c)	Riding Quality			√8 /U		
ď)	Road Camber ,			√\$⁄U		
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.					
f)	Contraction Joints provided or not (CC Pavement)					
g)	Compaction of flank/slope & raincuts if any					
*	Cross Brainage					
a)	Condition of head walls in Hume pipe culverts including its painting S/SRI/U					
b)	Condition of Abutment & Wing walls, Slab in RCC culverts S/SRI/U					
c)	Condition of railings/slab/approach for Bridges S/SRI/U					
3.	Road Furniture					
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained					
4	Congillance History					
a)	Status of ATR's & any others NO					
Overall Rating : Satisfactory (S)						

f		
Satisfactory (S)	2	
Satisfactory but requires Improvement (SRI)		
Unsatisfactory (U)		

(Signature)

NAME:

P.D. Chaulan

DESIGNATION:

J. E

Scanned by CamScanner