

FIELD INSPECTION REPORT

Date of Inspection :	District: <i>Darbhanga</i>
Division : <i>Darbhanga - I</i>	Length (km): <i>0630</i>
Name of the Road: <i>Pipraula main road near the house to Ghatol</i>	
Scheme/Programme:	MAINTENANCE
Package No.: <i>N/A</i>	Road Id No.: <i>N/A</i>
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓ <i>Flanks not available due to private land.</i>
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U <i>N/A</i>
c)	Condition of railings/slab/approach for Bridges	S/SRI/U <i>N/A</i>
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	<i>N/A.</i>

Overall Rating :

Satisfactory (S)	<i>S</i>
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	


(Signature)

NAME: *ARUNKUMAR*

DESIGNATION: *JE*