

FIELD INSPECTION REPORT

Date of Inspection: 14-1-2021	District: GAYA	
Division: Neeanchal Bahadur	Length (Km.): 1.115	
Scheme/Programme:	MAINTENANCE	
Package No.: Lo 61-Samudra 10 Gromudh (UPHE)	Road Id. No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance:	
Work is a case of:	New Connectivity/Up gradation/Maintenance	
Sl. No.	Parameters to be checked	Remarks
1	Pavement	
a)	Road Junction condition	S S/U
b)	Condition of Surfacing	S S/U
c)	riding Quality	S S/U
d)	Road Camber	S S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	HA Yes/No
f)	Contraction Joints provided or not (CC Pavement)	HA Yes/No
g)	Compaction of flanks/slope & raincuts if any	S Yes/No
2	Gross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S S/SR/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	HA S/SR/U
c)	Condition of railings/slab approach for Bridges	HA S/SR/U
3	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4	Compliance History	
a)	Status of ATRs & any others	No ATR

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Chatepar
14-1-2021
J.E