

FIELD INSPECTION REPORT

Date of Inspection: 14-1-2021		District: GAYA	
Division: Narmada-Balharani		Length (Km.): 0.928	
Scheme/Programme:		MAINTENANCE	
Package No.: L048-Sarbahada-Khualagan		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/Maintenance	
Parameters to be checked		Remarks	
Sl. No.			
1	Pavement	S	S/U
a)	Road Junction condition	S	S/U
b)	Condition of Surfacing	S	S/U
c)	Finishing Quality	S	S/U
d)	Road Camber	Yes	Yes/No
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes	Yes/No
g)	Compaction of flank/slope & raincuts if any		
2	Cross Drainage	SRI	S/SRI/U
a)	Condition of head walls in Hume pipe culverts including its painting	HA	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	HA	S/SRI/U
c)	Condition of railings/slab/approach for Bridges		
3	Road Furniture		Yes/No
a)	Whether sign boards/informatory/cautionary Board/1km & 200m stones/Pavement road markings are provided and maintained		
4	Compliance History	ATR	
a)	Status of ATR's & any others.		

Overall Rating

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

SRI

Chate Pal
14-1-2021
J.E