

FIELD INSPECTION REPORT

Date of Inspection: 14-1-2021		District: GAYA	
Division: Narmada-Bharani		Length (Km.): 1.5	
Scheme/Programme:		MAINTENANCE	
Package No.: Logo Duttah Bigha to Sonag (NAG)		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Upgradation/Maintenance	
Parameters to be checked		Remarks	
Sl. No.			
1	Pavement	S	S/U
a)	Road Junction condition	S	S/U
b)	Condition of Surfacing	S	S/U
c)	Grading Quality	S	S/U
d)	Road Camber	HA	Yes/No
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	HA	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes	S/SR/U
2	Cross-Drainage	HA	S/SR/U
a)	Condition of head walls in Hume pipe culverts including its painting	HA	S/SR/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	HA	S/SR/U
c)	Condition of railings/slab/approach for Bridges	Yes	Yes/No
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/Km & 200m stones/Pavement road markings are provided and maintained	Yes	Yes/No
4	Compliance History	No ATR	
a)	Status of ATRs & any others.	SR1	

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SR)	
Unsatisfactory (U)	

checked by
14-1-2021
J.E