FIELD INSPECTION REPORT

Date of I	nspection:	22/12/2020,	District: Patna	
Division	· Patra		Length (km): 0.555	
Name of	the Road: Sa	id Pus cha	udasi Path to yaman.	W29.
		AINTENANCE /	Nabard.	
Package		/	Road Id No.:	
Status of the Project: Ongoing/Completed/Under Maintenance				
Work is	a case of:	New Connectivity/U	p gradation/ Mainterlance	
Sl. No.	Parameters to be checked			Remarks
1.	Pavement			
a)	Road Junction condition			S/U
b)	Condition of Surfacing			S/U
c)	Riding Quality			S/U
d)	Road Camber			S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U /
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4.	Compliance His	tory		

Overall Rating

a)

Satisfactory (S) Satisfactory but requires Improvement (SRI) Unsatisfactory (U)

c(9)=

NAME: Jaifrakash Singh.
DESIGNATION: J.E.

Status of ATR's & any others