

FIELD INSPECTION REPORT

Date of Inspection :	10-1-21	District:	Gurgaon
Division :	RWD Gurgaon	Length (km):	1.559 km
Name of the Road:	Lohi Bazar to Karmatpur		
Scheme/Programme:	MAINTENANCE	P.M-1.3.3	
Package No.:	BR 12-R-632	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance <input checked="" type="checkbox"/>		
Work is a case of:	<input checked="" type="checkbox"/> New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	/ S/U
b)	Condition of Surfacing	/ S/U
c)	Riding Quality	/ S/U
d)	Road Camber	/ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	/ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	/ Yes/No
g)	Compaction of flank/slope & raincuts if any	/ Yes/No
	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	/ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA
	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	/ Yes/No
	Computerized History	
a)	Status of ATR's & any others	NA

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Accd
10-1-21
(Signature)

NAME:

Anil Kumar Mehta

DESIGNATION:

A.E.R. Gurgaon