

FIELD INSPECTION REPORT

Date of Inspection:	23/12/2020	District:	Sheerkhura
Division:	Sheerkhura	Length (km):	1.20 km
Name of the Road:	Bariya Bigha to Kripa bigha		
Scheme/Programme:	MAINTENANCE MMGSY (Gen) (Under 5 yrs Maint)		
Package No.:	Road Id No.:		
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/Maintenance		
S.No.			
Remarks			
Have you checked:			
a)	Road Junction condition	✓	S/U
b)	Condition of Surfacing	✓	S/U
c)	Riding Quality	✓	S/U
d)	Road Camber	✓	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓	Yes/No
g)	Compaction of flank/slope & raincuts if any	✓	Yes/No
If any defects found:			
a)	Condition of head walls in Hume pipe culverts including its painting	✓	S/SR/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓	S/SR/U
c)	Condition of railings/slab/slopes for Bridges	✓	S/SR/U NA
Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓	Yes/No
Other Remarks			
a)	Status of ATR's & any others		

Raincuts found at some places.

Sign Board/Informatory Board, km, 200m stones not maintained properly.

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires improvement (SRI)	SRI
Unsatisfactory (U)	—

S.H.
23/12/2020
(Signature)

NAME: SANGRAM HEMBROM

DESIGNATION: A.E.