

FIELD INSPECTION REPORT

Date of Inspection: 15/1/2021		District: W. Champaran
Division: R.W.D. Bettahat		Length (km): 1.8 km
Name of the Road: Goleb Chowk Pichet do Sissua		
Scheme/Programme: MAINTENANCE		
Package No.:		
Status of the Project:		Road Id No.: 318DPE 02289
Work is a case of:		Ongoing/Completed/Under Maintenance
		New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	/S/U
b)	Condition of Surfacing	/S/U
c)	Riding Quality	/S/U
d)	Road Camber	/S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	/Yes/No
f)	Contraction Joints provided or not (CC Pavement)	/Yes/No
g)	Compaction of flank/slope & raincuts if any	/Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	/S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	/S/SRI/U
c)	Condition of railings/slab/approach for Bridges	/S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	/Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	/

Overall Rating :

Satisfactory (S)

S

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

(Signature)

NAME:

DESIGNATION:

[Handwritten Signature]
15/1/2021
a