## FIELD INSPECTION REPORT

Date of Inspections:			District: Shee Chana.	
Division: Cher Chipura. Length (km):			Length (km): 0.7-69	3 Km.
Name of		himani	More To Muraz Du	
Scheme/P	rogramme:	MAINTENANCE	MMG34(50)	0
Package l			Road Id Not	
			Ongoing/Completed/Under Maintenance	
Worldis a case of:		NUMBER OF STREET	Up gradation/Maintenance	MANUAL PRODUCTION OF THE PARTY.
SIEDOR		Phanciere	o he theolad	Kempile -
115	Phyement 2			
a)	Road Junction condition			S/U
b)	Condition of Surfacing			/8/U
c)	Riding Quality			S/U
d)	Road Camber			/8/U
e) .	Whether free from defects such as visible cracks, exposed aggregates in case of CC Payement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No .
1000	Cross Drainings			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			s/srl/u
	Road Tubiliture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
	Compliance with long and the second second			
a)	Status of ATR's & any others			
Const	Dating			4
Overal	Rating :	Satisfactory (S)		5
Satisfactory but requires Improvement (S Unsatisfactory (U)				
			(U)	-

(Signature)

Tola.

NAME: SANGRAM HEMBROM

DESIGNATION: A.E.