

FIELD INSPECTION REPORT

Date of Inspection :		District: <u>Darbhanga</u>
Division : <u>Darbhanga - 1</u>		Length (km): <u>0.218</u>
Name of the Road: <u>REO path to chandanpatti pachhem</u>		
Scheme/Programme:		MAINTENANCE ✓
Package No.: <u>N/A</u>		Road Id No.: <u>N/A</u>
Status of the Project:		Ongoing/Completed/Under Maintenance
Work is a case of:		New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U <u>N/A</u>
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U <u>N/A</u>
c)	Condition of railings/slab/approach for Bridges	S/SRI/U <u>N/A</u>
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	<u>N/A</u>

Overall Rating :

Satisfactory (S)	<u>S</u>
Satisfactory but requires Improvement (SRI)	<u>-</u>
Unsatisfactory (U)	<u>-</u>


(Signature)

NAME: ARUN KUMAR

DESIGNATION: JE