

FIELD INSPECTION REPORT

Date of Inspection :	09/12/2020	District:	DARBHANGA.
Division :	DARBHANGA-1.	Length (km):	0.550 Km.
Name of the Road:	MUKHYA SADAK BALWAHA TO PICHARA BASTI BALWAHA		
Scheme/Programme:	MAINTENANCE		
Package No.:	N/A	Road Id No.:	N/A.
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	VS/U
b)	Condition of Surfacing	VS/U
c)	Riding Quality	VS/U
d)	Road Camber	VS/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No Rain Cuts.
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)	N/A.
Satisfactory but requires Improvement (SRI)	SRI.
Unsatisfactory (U)	N/A.

Painting of Road required.
from
 09/12/20

NAME:

DESIGNATION:

Manohar Lal Ram
 J.E.

(Signature)
 (Manik Lal Singh)
 A.E.