

# **FIELD INSPECTION REPORT**

<b>Date of Inspection :</b> 09/12/2020.		<b>District:</b> DARBHANGA.
<b>Division :</b> DARBHANGA-1.		<b>Length (km):</b> 0.850 K.M.
<b>Name of the Road:</b> ANANDPUR PWD ROAD TO MADHUPATI MAHABALITOLA.		
<b>Scheme/Programme:</b> MAINTENANCE ✓		
<b>Package No.:</b> N/A	<b>Road Id No.:</b> N/A.	
<b>Status of the Project:</b> Ongoing/Completed/Under Maintenance		
<b>Work is a case of:</b> New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
<b>1.</b>	<b>Pavement</b>	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank/slope & raincuts if any	✓Yes/No Rain cuts
<b>2.</b>	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓S/SRI/U
<b>3.</b>	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
<b>4.</b>	<b>Compliance History</b>	
a)	Status of ATR's & any others	N/A.

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	N/A
Unsatisfactory (U)	N/A

NAME: ARUN KUMAR

DESIGNATION: JE

(Signature)

09/12/20