

FIELD INSPECTION REPORT

| | |
|---|--|
| Date of Inspection : 10/12/20 | District: Siwan |
| Division : maharajganj | Length (km): 1.30 Km |
| Name of the Road: Dheba to La to Ramibari Bazar | |
| Scheme/Programme: MAINTENANCE | GTSNY |
| Package No.: | Road Id No.: |
| Status of the Project: | Ongoing Completed/Under Maintenance ✓ |
| Work is a case of: | New Connectivity/Up gradation/ Maintenance |

| Sl. No. | Parameters to be checked | Remarks |
|---------|---|----------------|
| 1. | Pavement P.C.C | |
| a) | Road Junction condition | ✓ S/U |
| b) | Condition of Surfacing | ✓ S/U |
| c) | Riding Quality | ✓ S/U |
| d) | Road Camber | ✓ S/U |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. | Yes/No ✓ |
| f) | Contraction Joints provided or not (CC Pavement) | Yes/No |
| g) | Compaction of flank/slope & raincuts if any | Yes/No ✓ |
| 2. | Cross Drainage | |
| a) | Condition of head walls in Hume pipe culverts including its painting | S/SRI/U ✓ |
| b) | Condition of Abutment & Wing walls, Slab in RCC culverts | N/A S/SRI/U |
| c) | Condition of railings/slab/approach for Bridges | N/A S/SRI/U |
| 3. | Road Furniture | |
| a) | Whether sign boards/informationary/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | Yes/No ✓ |
| 4. | Compliance History | |
| a) | Status of ATR's & any others | No any |

Overall Rating :

| | |
|---|---|
| Satisfactory (S) | — |
| Satisfactory but requires Improvement (SRI) | — |
| Unsatisfactory (U) | U |

Ram Sagar Das

NAME:

DESIGNATION:

J.E

10/12/20
(Signature)

Interst & road damaged from flood