

# FIELD INSPECTION REPORT

Date of Inspection : 04.01.2021  
 Division : Beland District : Sidamarkh.  
 Name of the Road: Ramavtar mangi house to Chandeshwar mangi house Length (km): 0.350 km  
 Scheme/Programme: MAINTENANCE GTSNY.  
 Package No.: Road Id No.:  
 Status of the Project: Ongoing/Completed Under Maintenance  
 Work is a case of: New Connectivity/Up gradation/ Maintenance

| Sl. No.   | Parameters to be checked                                                                                             | Remarks |
|-----------|----------------------------------------------------------------------------------------------------------------------|---------|
| <b>1.</b> | <b>Pavement</b>                                                                                                      |         |
| a)        | Road Junction condition                                                                                              | ✓S/U    |
| b)        | Condition of Surfacing                                                                                               | ✓S/U    |
| c)        | Riding Quality                                                                                                       | ✓S/U    |
| d)        | Road Camber                                                                                                          | ✓S/U    |
| e)        | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | ✓Yes/No |
| f)        | Contraction Joints provided or not (CC Pavement)                                                                     | ✓Yes/No |
| g)        | Compaction of flank/slope & raincuts if any                                                                          | ✓Yes/No |
| <b>2.</b> | <b>Cross Drainage</b>                                                                                                |         |
| a)        | Condition of head walls in Hume pipe culverts including its painting                                                 | S/SRI/U |
| b)        | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | S/SRI/U |
| c)        | Condition of railings/slab/approach for Bridges                                                                      | S/SRI/U |
| <b>3.</b> | <b>Road Furniture</b>                                                                                                |         |
| a)        | Whether sign boards/informatory/cautionary Board/km & 200m stones Pavement road markings are provided and maintained | ✓Yes/No |
| <b>4.</b> | <b>Compliance History</b>                                                                                            |         |
| a)        | Status of ATR's & any others                                                                                         |         |

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

S

S

—

(Signature)

NAME: Vikas Kumar